

Top 10 rules for Process Safety





Maintain a chronic sense of unease: The absence of evidence of risk is not evidence of the absence of risk. Measure and report PSM performance using meaningful indicators across the organization.

Read more about the Top 10 Rules for Process Safety and how you can leverage them for an effective PSM program.



DEKRA Process Safety North America www.dekra.us/process-safety

©2022 DEKRA North America, Inc., or its subsidiaries. All rights reserved. All trademarks are owned by DEKRA North America, Inc., or its subsidiaries, reg. U.S. Pat. & Tm. Off. and other countries as listed on our website.

